

Washington, D. C.

16 August 1963

25X1A

25X1A

Dear Alex:

In reply to your correspondence of 13 August 1963. I would appreciate it if you would send the following information [redacted]

25X1A

1. The teletype connector to be used will be a Amphenol type 126-217 connector which will plug into a Amphenol type 126-216 connector to be mounted on your rack.

2. A conventional line relay will be used instead of the Selector Magnet Driver as previously mentioned.

I would like to point out that in the circuit designed to time out and give an alarm if an acknowledge or error signal is not received in the specified interval, it will be necessary to have some easy method to reset the alarm circuit to allow subsequent transmission attempts.

I believe this should be clear [redacted] however, if there is any doubt, please contact me.

25X1A

Sincerely yours,

SIGNED

25X1A

Distribution:

Orig & 1 - Addressee
1 - Subject File
1 - Chrono

NPIC/P&DS:JPR;jn [redacted] 16 August 1963

25X1A

Declass Review by NIMA/DOD